





11 / 12 Inch Dry Vacuum
Machine Head





Rating Label	
1	Company Name & Address
2	Model
3	Voltage / Alternating Current
4	Frequency
5	Rated Input Power
6	Weight
7	WEEE Logo
8	Protection Class 2 Symbol
9	Approval Mark
10	Machine yr/wk Serial Number

12 Inch Wet Vacuums






Rating Label	
1	Company Name & Address
2	Model
3	Voltage/Alternating Current
4	Frequency
5	Rated Input Power
6	Weight
7	Ingress Protection
8	WEEE Logo
9	Protection Class 2 Symbol
10	Approval Mark
11	Machine yr/wk Serial Number

12 Inch Metal Head Vacuums





Rating Label	
1	Company Name & Address
2	Model
3	Voltage/Alternating Current
4	Frequency
5	Rated Input Power
6	Weight
7	Ingress Protection
8	WEEE Logo
9	Protection Class 2 Symbol
10	Approval Mark
11	Machine yr/wk Serial Number

12 Inch Wet Vacuums






Rating Label	
1	Company Name & Address
2	Model
3	Voltage / Alternating Current
4	Frequency
5	Rated Input Power
6	Weight
7	WEEE Logo
8	Protection Class 2 Symbol
9	Approval Mark
10	Machine yr/wk Serial Number





Rating Label	
1	Company Name & Address
2	Model
3	Voltage/Alternating Current
4	Frequency
5	Rated Input Power
6	Weight
7	MAX Pressure
8	Ingress Protection
9	WEEE Logo
10	Protection Class 2 Symbol
11	Approval Mark
12	Machine yr/wk Serial Number

RSB (Ruc Sac Vac)




Rating Label	
1	Voltage / Direct Current
2	Rated input power
3	Weight (ready to work)
4	Company name & address
5	Model
6	Machine yr/wk Serial number
7	Approval Mark
8	WEEE Logo
9	Use Lithium-Ion Battery Only

14 Inch Dry Vacuums



Rating Label	
1	Company Name & Address
2	Model
3	Voltage/Alternating Current
4	Frequency
5	Rated Input Power
6	Weight
7	Ingress Protection
8	WEEE Logo
9	Protection Class 2 Symbol
10	Approval Mark
11	Machine yr/wk Serial Number

14 Inch Wet Vacuums



1

Numatic
International Ltd.
CHARD, ENGLAND, TA202GB

3

2

3

***V~

4

5

**Hz

4

5

****W

6

7

**kg

6

7

IPX*

Name and
Address
of EU
Importers
in Manual

8

9


10

9

11

S/N:*****



Rating Label	
1	Company Name & Address
2	Model
3	Voltage/Alternating Current
4	Frequency
5	Rated Input Power
6	Weight
7	Ingress Protection
8	WEEE Logo
9	Protection Class 2 Symbol
10	Approval Mark
11	Machine yr/wk Serial Number



1	Numatic International. Ltd CHARD, ENGLAND, TA20 2GB	4	IPX 4
2	230V~ 50 Hz 400W	5	WEEE Logo
3	Approvals Mark	6	25.4Kg
	Barcode	7	094709460

Rating Label	
1	Company Name & Address
2	Voltage Frequency
3	Approvals Mark
4	Ingress Protection Rating
5	WEEE Logo
6	Weight (ready to use)
7	Machine yr/wk Serial number

Rotary Floor Machine



Numatic
International Ltd
Chard, England. TA20 2GB

HFM 1515

IPX4

32 kg

102714216

220-240V 50Hz
1500W
150RPM
INPUT WITH DUSTROL
2350w TOTAL

Diagram illustrating the components of the HFM 1515 machine, numbered 1 through 10:

1. Input power cord
2. Input power cord
3. Input power cord
4. Input power cord
5. Input power cord
6. Input power cord
7. Input power cord
8. Input power cord
9. Input power cord
10. Input power cord

Rating Label	
1	Voltage
2	Frequency
3	Rated Input Power
4	Weight (ready to work)
5	Company Name & Address
6	Model
7	Machine yr/wk Serial number
8	WEEE Logo
9	Protection Class 2 Symbol
10	Approvals Mark

Twintec - NUC244



1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

Numatic International Ltd

CHARD, ENGLAND, TA20 2GB

Model XXXXX

Battery Voltage XXV

Noise Emission XXdB(A)

HAV XX m/s²

RTU XX kg

IPXX

XX %

Use Lithium Ion Battery: PIN *****
Utilisez uniquement une batterie
lithium-ion PIN *****

Sku/Part



000000

For support goto

https://numqr.com


Rating Label	
1	Company Name & Address
2	Machine Description
3	Battery Voltage
4	Noise Emission
5	Hand Arm Vibration
6	Weight (ready to use)
7	Ingress Protection Rating
8	Gradient symbol
9	EU Importers info
10	Battery part number
11	Machine QR code
12	Approvals Mark
13	WEEE symbol
14	Part Number
15	Machine yr/wk Serial number
16	Numatic Support

Twintec - 1840




Rating Label

1	Company Name & Address
2	Model
3	Voltage / Direct Current
4	Rated Input Power
5	WEEE Logo
6	Ingress Protection
7	Max Gradient
8	Approval Mark
9	Weight (ready to use)
10	Machine yr/wk Serial Number
11	Model
12	Noise Rating
13	Hand Arm Vibration



Walk behind Twintecs



1

3

5

7

9

11

14

Numatic International Ltd

CHARD, ENGLAND, TA20 2GB

Model *****/***

Supply ***A ~ ***.***V ~ **.*Hz

Charger Output ***W

Battery Voltage **V ---

Noise Emission ≤ **.*dB(A)

HAV **.* m/s²

RTU XXX kg

IPX*

△

***%

Disconnect the supply before making or breaking connections to the battery.

Débrancher l'alimentation avant de brancher ou débrancher la batterie

Skul/Part *****

2

4

6

8

10

12

13

1

NUMATIC

International Ltd

CHARD, ENGLAND, TA20 2GB

Model: *****/*** RTU: ***.kg

Model: *****/*** RTU: ***.kg

Model: *****/*** RTU: ***.kg

Model: *****/*** RTU: ***.kg

2

8



Rating Label	
1	Company Name & Address
2	Machine Description
3	Supply Current / Voltage / Alternating Current / Frequency
4	Charger Output
5	Battery Voltage
6	Noise Rating
7	Hand Arm Vibration
8	Weight (ready to use)
9	Ingress Protection Rating
10	Max Gradient
11	QR Code
12	WEEE Logo / Approvals Mark
13	SKU / Part
14	Machine yr/wk Serial number

Ride-On Twintecs



1

3

5

7

9

11

14

Numatic International Ltd

CHARD, ENGLAND, TA20 2GB

Model *****/*

Supply ***A ~ ***.***V ~ **.*Hz

Charger Output ***W

Battery Voltage **V ---

Noise Emission ≤ **.*dB(A)

HAV *.* m/s² WBV *.* m/s²

RTU XXX kg

IPX*

Name and address of EU Importers in manual

Disconnect the supply before making or breaking connections to the battery.
Débrancher l'alimentation avant de brancher la batterie

QR Code

Skul/Part *****

0000000000

2

4

6

15

8

10

12

13

1

NUMATIC

International Ltd

CHARD, ENGLAND, TA20 2GB

Model: *****/* RTU: ***.kg

Model: *****/* RTU: ***.kg

Model: *****/* RTU: ***.kg

Model: *****/* RTU: ***.kg

2

8

Rating Label	
1	Company Name & Address
2	Machine Description
3	Supply Current / Voltage / Alternating Current / Frequency
4	Charger Output
5	Battery Voltage
6	Noise Rating
7	Hand Arm Vibration
8	Weight (ready to use)
9	Ingress Protection Rating
10	Max Gradient
11	QR Code
12	WEEE Logo / Approvals Mark
13	SKU / Part
14	Machine yr/wk Serial number
15	Whole Body Vibration

Ride-On Twintecs



1

3

5

7

9

11

14

Numatic International Ltd

CHARD, ENGLAND, TA20 2GB

Model *****/*

Supply ***A ~ ***.***V ~ **.*Hz

Charger Output ***W

Battery Voltage **V ---

Noise Emission ≤ **.*dB(A)

HAV *.* m/s² WBV *.* m/s²

RTU XXX kg

IPX*

△ **%

Disconnect the supply before making or breaking connections to the battery.
Débrancher l'alimentation avant de brancher ou débrancher la batterie

Skü/Part *****

0000000000

2

4

6

15

8

10

12

13

1

NUMATIC

International Ltd

CHARD, ENGLAND, TA20 2GB

Model: *****/* RTU: ***.kg

Model: *****/* RTU: ***.kg

Model: *****/* RTU: ***.kg

Model: *****/* RTU: ***.kg

2

8

Rating Label	
1	Company Name & Address
2	Machine Description
3	Supply Current / Voltage / Alternating Current / Frequency
4	Charger Output
5	Battery Voltage
6	Noise Rating
7	Hand Arm Vibration
8	Weight (ready to use)
9	Ingress Protection Rating
10	Max Gradient
11	QR Code
12	WEEE Logo / Approvals Mark
13	SKU / Part
14	Machine yr/wk Serial number
15	Whole Body Vibration